

1. EVALUATION PHASE

EVALUATE
SET EXPECTATIONS
(Test Area)

2. PREPARATION PHASE

HEAVY*	LIGHT*
HEAVY PREPARATION <small>Refer to EDCO's Surface Preparation Application Guide at edcoinc.com</small> <ul style="list-style-type: none"> • Coating Removal • Cracks & Lifts • Heavy Texture • Bird Baths • Spalling 	DRY PREP KIT Steps 1 2 3 30MD 70MD 120MD

* Based on slab conditions

3. POLISHING PHASE

HONING	POLISHING						
APPLY DENSIFIER <small>(LS Densifier)</small>				SEAL <small>(LS Shield)</small>			
Steps 1 2 3 4 5 6 7 8 50R 100R 200R Apply 400VH 800VH 1800VH 3500VH BUFF/BURNISH							

Accessory Key

- MD = Metal Bond Dots
- R = Resin Bond Discs
- VH = V-HARR™ Felt Pad

HONING/POLISHING



HONING/POLISHING